Fig.1




Fig.2




Fig.3(a)




Fig.3(b)






Fig.4








Fig.7

RELATIVE POSITIONAL DEVIATION (RESULT OF OVERLAY MEASUREMENT)




Fig.8





Fig.9






Fig.11

RELATIVE POSITIONAL DEVIATION (RESULT OF OVERLAY MEASUREMENT)




Fig.12

RIGHT EXPOSURE RELATED TO A MISSING LINE PATTERN AT ONE END

